

FLYSHEET AN-46
SELLER TEST DATA REQUIREMENTS

Seller is required to provide a copy of the attribute test data from all Quality Conformance Inspection (QCI) Group testing for each part number of military specification/drawing QML/QPL parts. The data shall clearly indicate the part numbers and date codes of parts used for QCI testing.

The test data shall be included with each part number shipment.