

IDS Common Quality Clauses

Q113 Traceability-Raw Material - rev 10/1/01

Seller shall mark each individual item and applicable documentation (i.e. test report, shipping report, or certification) to show clear traceability to lot, heat lot, or batch number. Unless otherwise directed by this purchase order/contract or the specification, when the size of the item does not permit marking of individual items, Seller shall label each package or box furnished.