

**IDS Terms and Conditions Guide**  
**Section Q**

**Clause Number: Q113**  
**Effective: 06/20/2008**  
**Page: 1 of 1**

TRACEABILITY-RAW MATERIAL

Seller shall mark each individual item and applicable documentation (e.g. test report, shipping report, or certification) to show traceability to lot, heat lot, material control or batch number. Unless otherwise directed by this contract, engineering drawing or the specification, when the size of the item does not permit marking of individual items, Seller shall label each package or box furnished.