

IDS Terms and Conditions Guide
Section Q

Clause Number: Q0120
Effective: 8/22/2005
Page: 1 of 1

**CALIBRATION SYSTEM AND NOTICE OF SIGNIFICANT OUT-OF-TOLERANCE
CONDITIONS**

The following requirements are applicable to this contract and are in addition to any other measurement and test equipment control requirements imposed by this contract:

A. Adequacy of the Calibration System:

The Seller shall maintain a system which evaluates the adequacy of their calibration system based on out-of-tolerance data as a result of calibrating the measuring and test equipment. This system shall include, but not be limited to, adjustment of calibration frequency, adequacy of the measuring or test equipment, calibration procedures and measuring or test procedures. The Seller's system shall specifically identify, and prevent the use of any measuring and test equipment that does not perform satisfactorily.

B. Notification of significant out-of-tolerance conditions:

Seller's system shall define a significant out-of-tolerance condition as any condition beyond 2 times the required accuracy. Seller's system shall include the requirement for notification of measurement and test equipment users, or other appropriate Seller elements, of significant out-of-tolerance conditions so appropriate actions can be taken to correct possible nonconforming goods.